Summary of Lower Platte, Elkhorn, and Missouri Rivers

Initial Ice Report 1/15/2023 through 1/21/2023:

There are no ice jams at this time.

Platte/Elkhorn River

E1 - Sarpy County

Submission Date: 1/18/2023 4:45:03 PM Feet Less Than Bankfull: 10 ft

Air Temperature (F): 28 °F Percent of Channel Open: 80%

Wind Speed (mph): NE 11 m.p.h. Type of Moving Ice:

Ice Jam Initial Condition:

Additional Comments

Elkhorn River is 95% open with no moving ice. Platte River is 75% open channel with no moving ice.

Platte River

PM4 - Douglas County

Submission Date: 1/18/2023 4:49:32 PM Feet Less Than Bankfull: 10 ft
Air Temperature (F): 29 °F Percent of Channel Open: 30%

Wind Speed (mph): NE 12 m.p.h. Type of Moving Ice:

Ice Jam Initial Condition:

Additional Comments

East channel has water on top of ice with no open channel. West Channel has an open channel along each bank with no moving ice. Each channel about 50'-75' wide.

Elkhorn River

PM6 - Douglas County

Submission Date: 1/18/2023 4:51:47 PM Feet Less Than Bankfull: 10 ft

Air Temperature (F): 33 °F Percent of Channel Open: 25%

Wind Speed (mph): NE 12 m.p.h. Type of Moving Ice:

Ice Jam Initial Condition:

Additional Comments

There is an open channel downstream of the bridge approximately 30' wide with no moving ice.

Elkhorn River

PM2 - Douglas County

Submission Date: 1/18/2023 4:54:25 PM Feet Less Than Bankfull:

Air Temperature (F): 33 °F Percent of Channel Open: 100%

Wind Speed (mph): NE 12 m.p.h. Type of Moving Ice:

Ice Jam Initial Condition:

Additional Comments

The river is wide open with no moving ice.

Platte River

PM7 - Douglas County

Submission Date: 1/18/2023 4:55:58 PM Feet Less Than Bankfull: 10 ft

Air Temperature (F): 33 °F Percent of Channel Open: 95%

Wind Speed (mph): NE 12 m.p.h. Type of Moving Ice:

Ice Jam Initial Condition:

Additional Comments

The channel is 95% open with no moving ice.

Elkhorn River

PM3 - Douglas County

Submission Date: 1/18/2023 5:00:15 PM Feet Less Than Bankfull: 10 ft

Air Temperature (F): 33 °F Percent of Channel Open: 40%

Wind Speed (mph): NE 12 m.p.h. Type of Moving Ice:

Ice Jam Initial Condition:

Additional Comments

There is an open channel approximately 35' wide with no moving ice.

Platte River

LS1 - Saunders County

Submission Date: 1/19/2023 4:30:01 PM Feet Less Than Bankfull: 5 ft

Air Temperature (F): 28 °F Percent of Channel Open:

Wind Speed (mph): NW 14 m.p.h. Type of Moving Ice:

Ice Jam Initial Condition:

Additional Comments

Most of the channel is open. Some ice still present along the right bank, with water pooled on top.

Platte River

LS2 - Cass County

Submission Date: 1/19/2023 5:04:09 PM Feet Less Than Bankfull: 6 ft

Air Temperature (F): 29 °F Percent of Channel Open:

Wind Speed (mph): NW 14 m.p.h. Type of Moving Ice: Frazil Slush

Ice Jam Initial Condition:

Additional Comments

Frazil slush moving in the channel leads me to think that the river is generating some ice. It is worth noting some ice and debris starting to build up in the middle of the bridge (picture attached). It looked like some of this ice is caught on sand in the channel.



Operator Reporting:	Miller		Email Report			
Date:	1/18/23		Save Report			
Time:	16:00		Print			
Loup River Conditions	i:	Diversion to canal -	Not Possible due to river conditions			
Loup River Ice Conditi	ons:	Heavy Slush				
Loup Hydro Canal Cor	nditions:	See Notes Below				
Notes:		and diversion into the	a Laura canal dua ta baggu angu aluah forming			
in the open river of	channel ι		E Loup canal due to heavy snow slush forming oa Headworks. Diversion will resume after			
slush clears in the	; river.					

For additional details, contact Columbus Powerhouse Operator 402-564-5280 hydroop@loup.com

Operator Reporting:	Miller			Email Report		
Date:	1/19/2023			Save Report		
Time:	1126			Print		
				11111		
Loup River Conditions	5 :	Divertible water to canal - Minimal				
Loup River Ice Conditi	ions:	See Notes Below				
Loup Hydro Canal Cor	nditions:	See Notes Below				
Notes:						
				e is still some ice debris		
moving nom upsu	ream to	the intake, preventing	IIICI ease diversion.			

For additional details, contact Columbus Powerhouse Operator 402-564-5280 hydroop@loup.com

Operator Reporting:	Baxa				Email Report
Date:	1-23-23	}			Save Report
Time:	0603				Print
Loup River Conditions	s:	Diversion to canal -	Not Possibl	e due to river	conditions
Loup River Ice Conditions:		Heavy Slush			
Loup Hydro Canal Conditions:		See Notes Below			
Notes:					
Diversion was shu	ut down a	at 0603 due to slush	in the river		

For additional details, contact Columbus Powerhouse Operator 402-564-5280

hydroop@loup.com

Operator Reporting:	Konwins	ski				Email Report
Date:	1-23-23					Save Report
Time:	0645					Print
Loup River Conditions	::	Divertible water to c	canal - Up	to 2000cfs		
Loup River Ice Conditions:		See Notes Below				
Loup Hydro Canal Cor	nditions:	Canal Ice Covered				
Notes:						
Headworks starting	ıg to dive	ert water again. There	e was jus	t a short time	e of heavie	r slush.

For additional details, contact Columbus Powerhouse Operator 402-564-5280 hydroop@loup.com