

Summary of Lower Platte & Elkhorn Rivers

Initial Ice Report 1/18/2021 through 1/21/2021:

NO ICE JAMMING AT THIS TIME on the East end of the State.

Elkhorn

PM2 - Douglas County, on the Elkhorn Hwy 36

Latitude: 41:22:45 Longitude: 96:18:9 (Wednesday, January 20, 2021 @ 9:05 AM)

Temperature was 31°F. The average wind speed was 11 mph (S). It is estimated that less than 10 feet bank full at this location. The channel remains 100%. It was noted: "none."

Elkhorn

PM3 - Douglas/Saunders County, on the Elkhorn Hwy 92

Latitude: 41:13:51 Longitude: 96:16:41 (Wednesday, January 20, 2021 @ 9:50 AM)

Temperature was 31°F. The average wind speed was 11 mph (S). It is estimated that less than 10 feet bank full at this location. Frazil-pans. The channel remains 95%. It was noted: "none."

Elkhorn

PM6 - Douglas County, on the Elkhorn Hwy 64

Latitude: 41:17:30 Longitude: 96:17:0 (Wednesday, January 20, 2021 @ 08:50AM CDT)

Temperature was 31°F. The average wind speed was 11 mph (S). It is estimated that less than 10 feet bank full at this location. Frazil-pans. The channel remains 95%. It was noted;" none."

Platte

PM4 - Douglas County, Hwy 92

Latitude: 41:14:2 Longitude: 96:21:55 (Wednesday, January 20, 2021 @ 8:30 AM)

Temperature was 31°F. The average wind speed was 11 mph (S). It is estimated that less than 10 feet bank full at this location. Freeze up growth is 5 feet from shore. Frazil-pans. The channel remains 60%. It was noted: " West channel is 90% open and the east channel is 25% open."

Platte

PM7 - Douglas County, Hwy 64

Latitude: 41:21:40 Longitude: 96:25:0 (Wednesday, January 20, 2021 @ 9:20 AM)

Temperature was 31°F. The average wind speed was 11 mph (S). It is estimated that less than 10 feet bank full at this location. The channel remains 80%. Frazil pans. It was noted:" None."

Platte

P7 – Sarpy County, Hwy 31 & I 80

Latitude: 41:1:27 Longitude: 96:15:29 (Wednesday January 20, 2021 @ 1:00 PM)

Temperature was 50°F. The average wind speed was 25 mph (SW). It is estimated that less than 3.1 feet Bank full at this location. The channel remains N/A%. Freeze up growth from shore is N/A feet. It was noted:" Channel was mostly clear of ice. Some frazil ice was floating."

Platte

P9 – Sarpy County, Hwy 6

Latitude: 41:3:42 Longitude: 96:19:31 (Wednesday January 20, 2021 @ 1:15 PM)

Temperature was 50°F. The average wind speed was 25 mph (SW). It is estimated that less than 5.1 feet Bank full at this location. The channel remains N/A%. Freeze up growth from shore is N/A feet. It was noted:” Channel is mostly clear of ice. No frazil or ice moving. There remains some intact ice along the two bridges.”

Platte

P10 – Sarpy County, Hwy 50 & Platte River Bridge

Latitude: 41:0:53 Longitude: 96:9:28 (Wednesday January 20, 2021 @ 12:45 PM)

Temperature was 50°F. The average wind speed was 25 mph (SW). It is estimated that less than 3.1 feet Bank full at this location. The channel remains N/A%. Freeze up growth from shore is N/A feet. It was noted:” Channel is almost 100% clear of ice. Just some small area of intact ice along the shore.”

Platte/Elkhorn

E1 - Sarpy County, on the Platte/Elkhorn Confluence of Platte and Elkhorn Rivers

Latitude: 41:8:0 Longitude: 96:19:0 (Wednesday, January 20, 2021 @ 8:00 AM)

Temperature was 31°F. The average wind speed was 11 mph (S). It is estimated that less than 10 feet bank full at this location. The channel remains 75%. It was noted: “Platte River is 75% open with frazil pans and the Elkhorn is also 75% open with frazil pans.”

