

Summary of Lower Platte & Elkhorn Rivers

Initial Ice Report 1/6/2022 through 1/13/2022:

Ice Jams are not present at this time on the eastern part of Nebraska.

Elkhorn

PM2 - Douglas County, on the Elkhorn Hwy 36

Latitude: 41:22:45 Longitude: 96:18:9 (Thursday, January 13, 2022 @ 9:23 AM)

Temperature was 27°F. The average wind speed was 5 mph (W). It is estimated that less than N/A feet bank full at this location. It was noted: "Some pockets of open water upstream and downstream of the bridge."

Elkhorn

PM3 - Douglas/Saunders County, on the Elkhorn Hwy 92

Latitude: 41:13:51 Longitude: 96:16:41 (Thursday, January 13, 2022 @ 9:26 AM)

Temperature was 34°F. The average wind speed was 5 mph (W). It is estimated that less than N/A feet bank full at this location. It was noted: "Some pockets of open water upstream and downstream of the bridge."

Platte

PM4 - Douglas County, Hwy 92

Latitude: 41:14:2 Longitude: 96:21:55 (Thursday, January 13, 2022 @ 9:20 AM)

Temperature was 26°F. The average wind speed was 5 mph (W). It is estimated that less than N/A feet bank full at this location. It was noted: "Both east and west channels are ice covered with some pockets of open water."

Platte

LS1 – Saunders County, Hwy 6

Latitude: 41:3:41 Longitude: 96:19:35 (Thursday, January 6, 2022 @ 10:30 AM)

Temperature was 4°F. The average wind speed was 16 mph (NW). It is estimated that less than 19 feet Bank full at this location. The channel remains 0%. 25% of open channel occupied by moving ice. It was noted: "None."

Platte

LS2 – Cass County, Hwy 50

Latitude: 41:0:47 Longitude: 96:9:27 (Thursday, January 13, 2021 @ 12:00 PM)

Temperature was 50°F. The average wind speed was 8 mph (NE). It is estimated that less than 9 feet Bank full at this location. Evidence of melting ice. 25% of open channel occupied by moving ice. It was noted: "River level is low at this location."